







Premium test stand in table-top version – now also with step motor

Features

- Motorised test stand for tension/compression force testing
- New: Step motor for greatest ease of use
 - for constant speed from the smallest to the
 - allows testing at minimum speed and full load
 - for higher positioning accuracy. Precise starting and stopping, without overrun, even at high speeds
 - precise adjustment of the process speed using the information shown on the display
- 2 A wide range of application possibilities because of its large travelling distance
- Automatic or manual process mode
- · Premium operating panel
 - Digital speed display

maximum load

- Digital repeat function
- Control of the test stand using PC software SAUTER AFH
- Table-top version for easy operation

- · Robust construction
- Fixation of SAUTER force measuring devices up to 2 kN possible
- • Solid and flexible possibilites of fixation of mouns for test objects, see accessory page 25 et seqq.
- The large diagram shows the TVO 1000N500S test stand with: SAUTER FH force measuring device, length measuring device SAUTER LD as well as mounts for the force measuring device and test objects, not supplied with the product

Technical data

- Speed accuracy: 1 % of [Max]
- Positioning accuracy when shutting down:
 ± 0,05 mm
- Dimensional drawings see instruction manual on www.sauter.eu

Accessories

- Digital length measuring device SAUTER LB, only for TVO 500N300S and TVO 500N300, SAUTER LB 300-2.
- Mounting the length measuring device onto a SAUTER test stand at the factory, SAUTER LB-A02
- Linear potentiometer for length measurement, measuring range: 225, 300, 500 or 700 mm, readout: 0.01 mm, for details see page 36, SAUTER LD
- Mounting the length measuring device onto a SAUTER test stand at the factory, SAUTER LD-A06
- Force-displacement data transfer software with graphical representation of the measuring process, only in combination with SAUTER LD, SAUTER AFH LD
- Force-time data transfer software for graphical representation on the PC and data transfer to Microsoft Excel®, SAUTER AFH FAST
- Force-displacement data transfer software with graphic display of the measurement process, SAUTER AFH FD
- Data transfer software for repeat tests, SAUTER AFH FGT
- Mount for force measuring devices of the SAUTER FH range with external load cell, SAUTER TVO-A01









Model	Measuring range	Speed range	Max. travelling distance 2	Dimensions W×D×H	
SAUTER	N	mm/min	mm	mm	
TVO 500N500S	500	1-500	300	236×428×570	
TVO 1000N500S	1000	1-500	500	265×405×980	
TVO 2000N500S	2000	1-500	700	300×465×1185	

SAUTER Pictograms:





Adjusting program (CAL):

For quick setting of the balance's accuracy. External adjusting weight required.



Control outputs

(optocoupler, digital I/O):

to connect relays, signal lamps, valves, etc.



Rechargeable battery pack:

rechargeable set.



PEAK

Calibration block:

Peak hold function:

measuring process.

standard for adjusting or correcting the measuring device.



Analogue interface:

to connect a suitable peripheral device for analogue processing of the measurements.



Mains adapter:

230V/50Hz in standard version for EU. On request GB, AUS or USA version available.



Statistics:

using the saved values, the device calculates statistical data, such as average value, standard deviation etc.



Power supply:

Integrated, 230V/50Hz in EU. More standards e.g. GB, AUS or USA on request.



Motorised drive:

The mechanical movement is carried out by a electric motor.



SCAN

Scan mode:

Push and Pull:

continuous capture and display of measurements.

capturing a peak value within a



PRINT

PC Software:

Printer:

to transfer the measurements from the device to a PC.

a printer can be connected to the

device to print out the measurements.



Motorised drive: The mechanical movement is carried out

by a synchronous motor (stepper).

DAkkS calibration possible:

is shown in days in the pictogram.



Length measurement:

and compression forces.

captures the geometric dimensions of a test object or the movement during a test process.

the measuring device can capture tension



GLP/ISO record keeping:

of measurements with date, time and serial number. Only with SAUTER printers.



Fast-Move:

the total length of travel can be covered by a single lever movement.



MEMORY

Focus function:

Internal memory:

to save measurements

in the device memory.

increases the measuring accuracy of a device within a defined measuring range.



Measuring units:

Weighing units can be switched to e.g. non-metric at the touch of a key. Please refer to website for more details.



Measuring with tolerance range

(limit-setting function): Upper and lower limiting can be programmed individually. The process is supported by an audible or visual signal, see the relevant model





DAkkS

+3 DAYS

Factory calibration:

The time required for factory calibration is specified in the pictogram.

The time required for DAkkS calibration



Data interface RS-232:

bidirectional, for connection of printer and PC.



Resets the display to "0".



Package shipment:

The time required for internal shipping preparations is shown in days in the pictogram.



Pallet shipment:

The time required for internal shipping preparations is shown in days in the pictogram.



Data interface USB:

To connect the balance to a printer, PC or other peripheral devices.



Data interface Infrared:

To transfer data from the balance to a printer, PC or other peripheral devices.



Battery operation:

Ready for battery operation. The battery type is specified for each device.

